



IMPORTANT - VIEWED FROM UNDERNEATH LID

Issues
Issue 2 June 7th 2000. Changed bolt holes to 11/32" and added "View from underneath"
Issue 3 June 13th 2000. Changed return hole to 1.5" diameter

Drawing No.	036		
Description	Stainless steel hinged lid		
Scale	1:2	Author	PJH
Date	June 6th 2000		
Issue	2		

