

Issue 3 Jan 26th 2016. Changed Sleeve diameter to 1.125". Renamed as new part 1088-18. See separate drg.

Issue 2 Jan 21st 2016. Altered flange to 2.75"

and added the cleaning sleeve dimension

The contents of this drawing are subject to copyright and must not be disclosed to a third party or reproduced without the permission of Powerwise Corp.

Drawing No.	1089-16-REM		
Description	Magnet Dipstick		
Scale	1/2	Author	PJH
Date	Jan 19th 2016		
Issue	3		